

August 2007

Date: 7/5/07

Requested by: Richard Sesma

Address: 3331 Madrona Drive

Location of Tree: 3331 Madrona Drive

Tree Species: Harpephyllum caffrum **Common Name:** KAFFIR PLUM

Requested Reason for Removal: Tree root is causing the sidewalk to lift up.

Species recommended by the Approved Plan:

Advisory Committee Recommendation: *Approve Removal:* *Deny Removal:*

Staff Recommendation: *Approve Removal:* *Deny Removal:*

Date Posted: 8/6/07

Comments: The Committee and staff determined that damage to the sidewalk was not a valid reason for removing this tree. Staff will contact Public Works to ensure that the appropriate actions are taken to repair the sidewalk damage at this location.

PHOTO INVENTORY

